



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
 County: Douglas
 Site ID: 8-16-29-1
 Facility Type: Hi-Arch
 Site Address: 7417 S. County Rd. E, Hawthorne
 Date: March 24, 2016
 Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Apron has moderate cracking.				X	
Ceiling and Roof	A few shingles missing. Roof functions as intended.			X		
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Ceiling and Roof