



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Douglas
Site ID: 8-16-31-1
Facility Type: Shed
Site Address: 15265 S. State Rd. 35, Dairyland
Date: March 23, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			