



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Dunn
Site ID: 6-17-1-2
Facility Type: Shed
Site Address: 3303 USH 12E, Menomonie
Date: February 10, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None	X				
Ceiling and Roof	None	X				
Walls	West wall is beginning to bow and several structural timbers are cracking.			X		
Doors	None		X			



Walls