




Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Dunn  
Site ID: 6-17-1-5  
Facility Type: Shed  
Site Address: 3303 USH 12E, Menomonie  
Date: February 10, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	North wall is beginning to bow.			X		
Doors	None		X			



Walls