



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Dunn
Site ID: 6-17-2-1
Facility Type: Shed
Site Address: N1156 939th St., Rock Falls
Date: February 10, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	Structural wall timbers are broken and not repaired.					X
Doors	Door handle is missing on left door, slight damage to door.			X		



Walls



Doors



Walls