



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
 County: Dunn
 Site ID: 6-17-3-1
 Facility Type: Shed
 Site Address: N7664 State Rd. 170, Colfax
 Date: February 9, 2016
 Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Small hole in roof and one broken truss that is unrepaired.				X	
Walls	Walls are slightly bowed and beginning to crack, picture was taken of west wall			X		
Doors	Door handle is broken.			X		



Ceiling and Roof



Walls



Doors