



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Dunn  
Site ID: 6-17-3-2  
Facility Type: Shed  
Site Address: N7664 State Rd. 170, Colfax  
Date: February 9, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Pad not visible, apron was in good condition		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			