



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Dunn  
Site ID: 6-17-33-2  
Facility Type: Hi-Arch  
Site Address: N12124 State Rd. 25, Wheeler  
Date: February 9, 2016  
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Pad not visible.		X			
Ceiling and Roof	None	X				
Walls	None	X				
Doors	None	X				