



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest
County: Eau Claire
Site ID: 6-18-1-2
Facility Type: Shed
Site Address: 2000 Spooner Ave., Altoona
Date: February 23, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	Siding on walls has some cracks, west wall is bowed.			X		
Doors	Doors are chipped/cracked and very difficult to function.			X		



Walls



Doors



Walls