



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Florence
Site ID: 7-19-106-2
Facility Type: Shed
Site Address: 4391 State Rd. 139, Long Lake
Date: March 1, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	Doors cracked and pieces missing.				X	



Doors



Doors