



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report




Region: North Central
County: Florence
Site ID: 7-19-6-2
Facility Type: Shed
Site Address: 5471 County Rd. N, Florence
Date: March 1, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large cracks in apron.				X	
Ceiling and Roof	None		X			
Walls	Broken support beam north wall.				X	
Doors	Door cracked and small piece missing.				X	



Apron and Pad



Walls



Walls



Door