



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Fond du lac
Site ID: 2-20-201-5
Facility Type: Dome
Site Address: 301 Dixie Street, Fond du lac
Date: March 09, 2016
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None	X				
Walls	None		X			
Doors	Rust at bottom of overhead door.				X	



Doors