



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Fond du lac  
Site ID: 2-20-202-1  
Facility Type: Dome  
Site Address: N5170 State Road 49, Brandon  
Date: March 08, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Some cracks in apron; no potholes.			X		
Ceiling and Roof	A few shingles missing near top of roof.			X		
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Ceiling and Roof