



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Forest  
Site ID: 7-21-110-1  
Facility Type: Shed  
Site Address: 4630 Runny Waters Road, Laona  
Date: March 1, 2016  
Inspector: Todd Laska

| Asset            | Comments                             | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 - Bad |
|------------------|--------------------------------------|---------------|----------|----------|----------|---------|
| Apron and Pad    | Moderate cracking on apron.          |               |          |          | X        |         |
| Ceiling and Roof | None                                 |               | X        |          |          |         |
| Walls            | Broken/missing shed boards, patched. |               |          |          | X        |         |
| Doors            | None.                                |               | X        |          |          |         |



Apron and Pad



Walls