



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Forest  
Site ID: 7-21-155-1  
Facility Type: Dome  
Site Address: 5360 County Rd. W, Crandon  
Date: March 1, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large cracks in apron.				X	
Ceiling and Roof	Shingles missing/weathered.				X	
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof