



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Grant
Site ID: 1-22-197-1
Facility Type: Shed
Site Address: 532 State Road 35, Bloomington
Date: March 2, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Some cracking in asphalt apron.			X		
Ceiling and Roof	None		X			
Walls	Wall slightly bowed.			X		
Doors	Bottom left corner damaged.			X		



Apron and Pad



Apron and Pad



Walls



Doors