



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Grant
Site ID: 1-22-387-2
Facility Type: Dome
Site Address: 9755 USH 61, Lancaster
Date: March 1, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	2 loose shingles			X		
Walls	None		X			
Doors	Bottom right hand corner of door damaged.			X		



Roof



Door