



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Grant
Site ID: 1-22-478-3
Facility Type: Hi-Arch
Site Address: 2771 Shoe String Rd. (Dickeyville), Cuba City
Date: March 2, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Assessment limited due to gravel on top of asphalt		X			
Ceiling and Roof	Shingles curling at some locations over lean-to on east side of Hi-Arch.			X		
Walls	None		X			
Doors	None		X			



Roof