



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Green Lake
Site ID: 4-24-5-5
Facility Type: Shed
Site Address: 570 South St., Green Lake
Date: February 8, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large cracks/some potholes in apron.				X	
Ceiling and Roof	Missing/weathered shingles.				X	
Walls	None			X		
Doors	None			X		



Apron and Pad



Ceiling and Roof