



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Green Lake
Site ID: 4-24-5-7
Facility Type: Dome
Site Address: 570 South St., Green Lake
Date: February 8, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			