



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Green Lake  
Site ID: 4-24-7-5  
Facility Type: Shed  
Site Address: N1906 State Rd. 73, Manchester  
Date: February 8, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Some missing and weathered shingles.				X	
Walls	None		X			
Doors	None		X			



Ceiling and Roof