



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
 County: Green  
 Site ID: 1-23-49-2  
 Facility Type: Dome  
 Site Address: 2813 6<sup>th</sup> St., Monroe  
 Date: February 22, 2016  
 Inspector: Todd Laska

| Asset                   | Comments                               | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 - Bad |
|-------------------------|--|---------------|----------|----------|----------|---------|
| <b>Apron and Pad</b>    | Multiple cracks and potholes in apron. |               |          |          | X        |         |
| <b>Ceiling and Roof</b> | None                                   |               | X        |          |          |         |
| <b>Walls</b>            | None                                   |               | X        |          |          |         |
| <b>Doors</b>            | No door.                               |               |          |          |          | X       |



Apron and Pad



Apron and Pad



Doors