



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Jackson  
Site ID: 5-27-601-3  
Facility Type: Shed  
Site Address: 23 Harrison Street, Black River Falls  
Date: March 22, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			