



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Jackson  
Site ID: 5-27-602-2  
Facility Type: Shed  
Site Address: W15622 County Rd. FF, Northfield  
Date: March 22, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
<b>Apron and Pad</b>	Large cracks/potholes in apron.				X	
<b>Ceiling and Roof</b>	None			X		
<b>Walls</b>	North wall patched with plywood.				X	
<b>Doors</b>	Door is missing pieces.				X	



Apron and Pad



Walls



Doors