



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northwest  
County: Jackson  
Site ID: 5-27-903-1  
Facility Type: Shed  
Site Address: Rest Area #58, EB I-94 Mile Marker 124  
Date: March 22, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
<b>Apron and Pad</b>	None	X				
<b>Ceiling and Roof</b>	None	X				
<b>Walls</b>	None	X				
<b>Doors</b>	None	X				