



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
 County: Juneau  
 Site ID: 4-29-144-1  
 Facility Type: Shed  
 Site Address: 605 John Street, Necedah  
 Date: March 29, 2016  
 Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
<b>Apron and Pad</b>	Some cracks in apron.			X		
<b>Ceiling and Roof</b>	Some weathered shingles.			X		
<b>Walls</b>	None		X			
<b>Doors</b>	Missing pieces near bottom of door.				X	



Apron and Pad



Ceiling and Roof



Doors