



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Juneau
Site ID: 4-29-204-2
Facility Type: Shed
Site Address: 305 Bickford Street, New Lisbon
Date: March 29, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Slight cracking on apron.			X		
Ceiling and Roof	Weathered shingles; roof functioning as intended.			X		
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Ceiling and Roof