



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: Juneau
Site ID: 4-29-85-2
Facility Type: Dome
Site Address: 930 East State Street, Mauston
Date: March 29, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracks in apron.			X		
Ceiling and Roof	A few missing/weathered shingles.				X	
Walls	None		X			
Doors	Base of door busting through.				X	



Apron and Pad



Ceiling and Roof



Doors