



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: Juneau  
Site ID: 4-29-86-1  
Facility Type: Shed  
Site Address: N3389 State Rd. 80, Elroy  
Date: March 29, 2016  
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	One cracked truss/rafter (unrepaired).				X	
Walls	Missing piece on interior wall.			X		
Doors	None		X			



Ceiling and Roof



Walls