



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast  
County: Kenosha  
Site ID: 2-30-1-1  
Facility Type: Dome  
Site Address: 5195 120<sup>th</sup> Ave., Kenosha  
Date: February 18, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			