



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: La Crosse  
Site ID: 5-32-651-1  
Facility Type: Shed  
Site Address: N5652 County Rd. OT, Onalaska  
Date: March 21, 2016  
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Large potholes in apron.				X	
Ceiling and Roof	Weathered shingles; roof still functioning as intended.			X		
Walls	None		X			
Doors	Slight damage to edge of door.			X		



Apron and Pad



Ceiling and Roof



Ceiling and Roof



Doors