



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: La Crosse
Site ID: 5-32-651-4
Facility Type: Shed
Site Address: N5652 County Rd. OT, Onalaska
Date: March 21, 2016
Inspector: Dick Thompson

| Asset | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 – Bad |
|------------------|--|---------------|----------|----------|----------|---------|
| Apron and Pad | None | | X | | | |
| Ceiling and Roof | Some weathered shingles; roof still functioning as intended. | | | X | | |
| Walls | None | | X | | | |
| Doors | None | | X | | | |



Ceiling and Roof