



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest
County: La Crosse
Site ID: 5-32-653-1
Facility Type: Dome
Site Address: N4922 Carlson Rd. West Salem
Date: March 22, 2016
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracking in apron.			X		
Ceiling and Roof	Some shingle tabs missing.				X	
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof



Ceiling and Roof