



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southwest  
County: La Crosse  
Site ID: 5-32-681-1  
Facility Type: Shed  
Site Address: Opposite 1405 County  
Rd SS, Onalaska  
Date: March 22, 2016  
Inspector: Dick Thompson

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	Some cracking in apron.			X		
Ceiling and Roof	Shingles curling and weathered; roof still functioning as intended.			X		
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof