



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Langlade
Site ID: 7-34-12-2
Facility Type: Shed
Site Address: N7520 School Rd., Lily
Date: February 29, 2016
Inspector: Todd Laska

| Asset | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 - Bad |
|-------------------------|----------|---------------|----------|----------|----------|---------|
| Apron and Pad | None | | X | | | |
| Ceiling and Roof | None | | X | | | |
| Walls | None | | X | | | |
| Doors | None | | X | | | |