



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Langlade  
Site ID: 7-34-13-1  
Facility Type: Dome  
Site Address: 1521 Arctic St., Antigo  
Date: February 29, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
<b>Apron and Pad</b>	None		X			
<b>Ceiling and Roof</b>	None		X			
<b>Walls</b>	None		X			
<b>Doors</b>	None		X			