



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Lincoln
Site ID: 7-35-14-4
Facility Type: Hi-Arch
Site Address: 100 Cooper St., Merrill
Date: February 16, 2016
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	New roof in 2015.	X				
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof



Ceiling and Roof