



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Lincoln  
Site ID: 7-35-14-6  
Facility Type: Dome  
Site Address: 100 Cooper St., Merrill  
Date: February 16, 2016  
Inspector: Eric Schmidt

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad



Ceiling and Roof



Doors