



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Manitowoc
Site ID: 3-36-22-5
Facility Type: Shed
Site Address: 318 W. Main St./CTH C, St. Nazianz
Date: March 23, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None	X				
Ceiling and Roof	None		X			
Walls	Wood siding is beginning to crack and splinter. A section of the wood siding is soft to the touch, and can be pulled apart.			X		
Doors	None		X			



Walls