



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Manitowoc
Site ID: 3-36-24-4
Facility Type: Shed
Site Address: 740 N. State Street/CTH B, Mishicot
Date: March 23, 2016
Inspector: Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			