



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Marinette  
Site ID: 3-38-110-5  
Facility Type: Dome  
Site Address: 130 Stephenson St., Peshtigo  
Date: February 3, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			