



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Marinette
Site ID: 3-38-111-3
Facility Type: Shed
Site Address: N18291 State Rd. 141, Pembine
Date: February 2, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Some cracking in apron.			X		
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			



Apron and Pad



Apron and Pad



Apron and Pad