



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central
County: Marquette
Site ID: 4-39-138-1
Facility Type: Dome
Site Address: W6316 State Rd. 23, Oxford (Packwaukee)
Date: February 8, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Missing shingles/fascia				X	
Walls	None		X			
Doors	None		X			



Ceiling and Roof