



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: North Central  
County: Menominee  
Site ID: 3-73-85-1  
Facility Type: Dome  
Site Address: W2703 Chief Carron Rd., Keshena  
Date: February 18, 2016  
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	Small indentation in roof where loader likely hit.			X		
Walls	None		X			
Doors	Door needs to be replaced, not operating correctly according to Jeremy Weso. Door header damaged.				X	



Ceiling and Roof



Doors