



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
 County: Oconto
 Site ID: 3-42-305-1
 Facility Type: Shed
 Site Address: 14068 Old Highway 32, Mountain
 Date: February 29, 2016
 Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	Multiple large cracks/potholes.				X	
Ceiling and Roof	Broken truss member, weathered shingles				X	
Walls	Small area of salt wicking through wood timber, shredding exterior of timber. Otherwise, walls functioning as intended.			X		
Doors	None		X			



Apron and Pad



Apron and Pad



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Ceiling and Roof



Ceiling and Roof



Ceiling and Roof



Walls