



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Oconto
Site ID: 3-42-52-1
Facility Type: Dome
Site Address: 202 Van Dyke St., Oconto
Date: March 3, 2016
Inspector: Todd Laska

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 - Bad
Apron and Pad	None		X			
Ceiling and Roof	None		X			
Walls	None		X			
Doors	None		X			