



Wisconsin Department of Transportation
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast
County: Outagamie
Site ID: 3-44-2-1
Facility Type: Shed
Site Address: 115 South Oak Street, Hortonville
Date: March 18, 2016
Inspector: Marcus Hopkins

| Asset | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 – Bad |
|-------------------------|----------|---------------|----------|----------|----------|---------|
| Apron and Pad | None | X | | | | |
| Ceiling and Roof | None | X | | | | |
| Walls | None | X | | | | |
| Doors | None | X | | | | |