



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Northeast  
County: Outagamie  
Site ID: 3-44-7-4  
Facility Type: Dome  
Site Address: 7517 STH 54, Shiocton  
Date: March 18, 2016  
Inspector: Marcus Hopkins

| Asset            | Comments | 1 – Excellent | 2 - Good | 3 – Okay | 4 – Poor | 5 – Bad |
|------------------|----------|---------------|----------|----------|----------|---------|
| Apron and Pad    | None     |               | X        |          |          |         |
| Ceiling and Roof | None     | X             |          |          |          |         |
| Walls            | None     | X             |          |          |          |         |
| Doors            | None     |               | X        |          |          |         |