

Wisconsin Department of Transportation Salt Shed Facilities Asset Management Condition Inspection Report



Region:	<u>Northeast</u>
County:	<u>Outagamie</u>
Site ID:	<u>3-44-9-1</u>
acility Type:	<u>Shed</u>
Site Address:	440 Municipal Drive, Seymour
Date:	<u>March 18, 2016</u>
nspector:	Marcus Hopkins

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		Х			
Ceiling and Roof	None	Х				
Walls	None	Х				
Doors	None	Х				