



Wisconsin Department of Transportation  
Salt Shed Facilities Asset Management Condition Inspection Report



Region: Southeast  
County: Ozaukee  
Site ID: 2-45-201-1  
Facility Type: Dome  
Site Address: 410 South Spring Street, Port Washington  
Date: March 10, 2016  
Inspector: Phil Eagan

Asset	Comments	1 – Excellent	2 - Good	3 – Okay	4 – Poor	5 – Bad
Apron and Pad	None		X			
Ceiling and Roof	Missing shingles				X	
Walls	None		X			
Doors	None		X			



Ceiling and Roof